


APPENDIX A:
SELECTED AREAS OF STUDY FOR THE SUPPLEMENTAL HSR

BARNSDALL ART PARK - HOLLYHOCK HOUSE



PHASE III

PORCH:



Major water leaks above the doorway.

FIRE PLACE:



Fire Place chimney need structural bracing.

FOUNTAIN:



Circle fountain, major feature of the Hollyhock House, needs minor repair.

PLAYROOM:




Structure cracks and unsealed roof tile cause water leaks.

GALLERY:



Water leaks above the window/doorway.



HOLLYHOCK HOUSE - FIRST FLOOR PLAN



BARNSDALL ART PARK - HOLLYHOCK HOUSE



GARAGE:




Phase I construction has strengthened the roof/ parapet only. The garage interior was left functional.

DINING ROOM:



Water ponding due to sagging roof framing.



N HOLLYHOCK HOUSE - ROOF PLAN

PORCH ROOF:



Repair porch roof water intrusion issue would involve reinstall the artstone / roof tiles.

LIBRARY EXTERIOR WALL:




Extensive structural cracks indicated problems at the foundation level.

TREE:



Existing tree caused patio structural damage.



APPENDIX B:
HISTORIC PHOTOGRAPHS OF SELECTED AREAS OF STUDY




Figure 1: Circa 1922 photo of Hollyhock House living room with fireplace, view southwest.
(Photo credit: Hollyhock House Archives)



Figure 2: Circa 1946 photo of living room fireplace, view southwest. Note pool surrounding fireplace has been covered over.
(Photo credit: Hollyhock House Archives)



Figure 3: Circa 1923 photo of living room, view northwest, note pool surrounding fireplace on bottom left corner of photo.
(Photo credit: Hollyhock House Archives)




Figure 4: Circa 1923 photo of living room fireplace with andirons visible, view southwest.
(Photo credit: Hollyhock House Archives)



Figure 5: Circa 1970 photo of living room fireplace, view southwest.
(Photo credit: Don Normark for Sunset Magazine, located at Hollyhock House Archives)



Figure 6: Circa 1945 photo of living room during an early renovation, view southwest.
(Photo credit: Will Connell Archives, located at the California Museum of Photography, UC Riverside)



Figure 7: Circa 1945 photo of living room during an early renovation, view southwest. Living room fireplace is visible to left of photograph. (Photo credit: Will Connell Archives, located at the California Museum of Photography, UC Riverside)



Figure 8: Circa 1945 photo of living room during an early renovation, view southeast. (Photo credit: Will Connell Archives, located at the California Museum of Photography, UC Riverside)




Figure 9: Circa 1920 photo of living room fireplace, view southwest.
(Photo credit: Hollyhock House Archives)



Figure 10: Circa 1980 photo of detail of living room fireplace, view southwest,
(Photo credit: Hollyhock House Archives)



Figure 11: 1995 photo of living room fireplace, view south.
(Photo credit: Tom Zimmerman, located at Hollyhock House Archives)




Figure 12: Circa 1925 photo of inner court showing porch roof to left of photo.
(Photo credit: Hollyhock House Archives)



Figure 13: Circa 1925-1926 photo of inner courtyard with porch roof.
(Photo credit: Will Connell Archives, located at the California Museum of Photography,
UC Riverside).




Figure 14: Circa 1924 detail photo of porch roof.
(Photo credit: Jean Armand, held at the Hollyhock House Archives)




Figure 15: Circa 1924 photo of porch roof.
(Photo credit: Jean Armand, held at the Hollyhock House Archives)




Figure 16: Circa 1923 photo of inner courtyard taken at ground level. Porch roof is to left of photo.
(Photo credit: Hollyhock House Archives)



Figure 17: Circa 1945 photo of gallery during an early renovation, view west.
(Photo credit: Will Connell Archives, located at the California Museum of Photography, UC Riverside)




Figure 18: Circa 1922 photo of courtyard with round fountain in foreground, view east.
(Photo credit: Hollyhock House Archives)




Figure 19: Circa 1927 photo of round fountain, view east.
(Photo credit: Hollyhock House Archives)




Figure 20: Circa 1923 photo of east elevation showing round fountain, view northwest.
(Photo credit: Jean Armand, Hollyhock House Archives)



Figure 21: Circa 1924 photo of round fountain filled with vegetation, view southwest.
(Photo credit: Hollyhock House Archives)



Figure 22: Square fountain along west elevation, view northeast. Date of photo unknown.
(Photo credit: Will Connell Archives, located at the California Museum of Photography, UC Riverside)



Figure 23: Detail photo of west elevation with square fountain near bottom left corner of photo, view northeast. Date of photo unknown.
(Photo credit: Will Connell Archives, located at the California Museum of Photography, UC Riverside)



Figure 24: Circa 1922-1923 photo with garage building in background, view north.
(Photo credit: Aline Barnsdall's personal album, held at Hollyhock House Archives)



Figure 25: Circa 1926-1927 photo showing garage building in background.
(Photo credit: Los Angeles Times photo, held at Hollyhock House Archives)



Figure 26: North elevation of garage building, view southeast. Date of photo unknown.
(Photo credit: Hollyhock House Archives)



Figure 27: Photo showing south elevation of garage building behind walkway, view northwest. Date of photo unknown.
(Photo credit: Hollyhock House Archives)



Figure 28: 1979 photo of garage building south and east elevations, view northwest.
(Photo credit: Hollyhock House Archives)



Figure 29: 1984 photo showing south elevation of garage building with remodeled entrance, view north.
(Photo credit: Dick Whittington, held at Hollyhock House Archives)



Figure 30: 1979 interior photo of garage building showing water damage.
(Photo credit: Hollyhock House Archives)